

RESULTS

DETERMINATION OF DIMENSIONAL CHANGE IN DOMESTIC WASHING AND DRYING

Standard : UNE-EN 25077

Preparation, marking and measuring of fabric specimens according to UNE-EN ISO 3759:1996

Washing procedure: 5A ($T^a=40\pm 3^{\circ}\text{C}$) according to UNE-EN 26330.

Number of washing cycles: 1

Drying procedure: Flat drying

<u>Reference</u>	<u>Number of specimens</u>	<u>Direction</u>	<u>Dimensional change (%)</u>
TEJIDO BALI	2	Warp	-0.6
		Weft	-1.6
TEJIDO DAMA	2	Warp	-0.5
		Weft	-1.2

REMARK: Negative dimensional change indicates shrinkage.