

RESULTS

RESISTANCE TO PILLING

Standard: ISO/DIS 12945-2

Apparatus: Martindale Abrasion Tester

Number of specimens: 3

Abradant: SM-25 woollen standard fabric

Testing Pressure: 415 ± 2 g

Number of cycles: 5000

<u>Reference</u>	<u>Pilling degree</u>
TEJIDO BALI	4-5
TEJIDO DAMA	4-5

INTERPRETATION OF THE PILLING DEGREE

- 5.- NO PILLING
- 4.- SLIGHT PILLING
- 3.- MODERATE PILLING
- 2.- SEVERE PILLING
- 1.- VERY SEVERE PILLING

